



---

## TECHNICAL INFORMATION BULLETIN

# 6T30E/40E/45E/50E Solenoid Blocks

These solenoid blocks come with the latest software version at the time of production. If this software is newer than the software in the vehicle, you will not be able to communicate with the new solenoid block.

If so, the car must be taken to the dealer to have the vehicle software updated to the latest version for the solenoid block to work.

If the vehicle software is up to date at the time of fitting the solenoid block, the vehicle will drive, but shift characteristics will be undesirable.

The vehicle should be taken to the dealer to have the adaption's set correctly after installation of the new solenoid pack.